






After Action Report

Topic: Germantown Festival		Date: Sept. 10, 2014	
	What was supposed to happen?		What actually happened?
Weekend event go off without having any plumbing, lighting or electrical problems.		There were no plumbing or lighting issues during event. Due to an excessively heavy rain Saturday afternoon, several of the pits filled up with water resulting in having to be pumped out. Due to run off water Saturday afternoon it did little good to pump pits out, so work had to be completed early Sunday morning. Some of the twist lock plugs were disconnected and dried before reconnecting and turning back on. All breakers were checked with only two being found tripped.	
	What worked well that needs to be sustained?		What did not work well and needs to be changed?
Prep work prior to any vendors arriving for setup. Staffing during event.		<ol style="list-style-type: none"> 1. Some of the pits or grade around them should have improvements made in order to redirect water runoff. 2. Smaller pump and hose purchased by festival group and kept in their storage for when this happens again. 3. Due to the water and dirt that has entered pits and disconnects over time, the years and condition on pit disconnects, some of these units should start being replaced. 4. Signage should be posted around grounds informing of additional restrooms at the C.O. Franklin building. This may help relieve crowds at Pickering. 5. Traffic appeared to be heavier within the festival grounds than in years past. (Maybe restrict lots to fewer parking passes or possible vendors park off site and bus in.) 	
What to do next? 			
Price replacement disconnects. Speak with festival group about purchasing water pump and hose for future events. Look at possible options on water entering electrical pits.			
AAR Participants Steve Williams, Mike Fronabarger w/Facility Services			